

JULY

REF	Parish/Ward	Road Name	Location	Type of Work Required	Comments	Confirm Number	Date Requested	Date Completed	STATUS
LHAR18-06-01	Harlow	Abercrombie Way	Opp L/C: 3579.	HW: verge damaged	Approximately 0.6 x 7.0 Metres Square. Verge. Topsoil.	3222847	11/05/2018	11/07/2018	complete
LHAR18-06-02	Harlow	Abercrombie Way	Opp L/C: 3599.	HW: verge damaged	Approximately 0.2 x 5.0 Metres Square. Verge. Topsoil.	3222834	11/05/2018	11/07/2018	complete
LHAR18-06-03	Harlow	Abercrombie Way	S/O L/C: 3573.	HW: verge damaged	Approximately 1.0 x 19.0 Metres Square. Verge. Topsoil.	3222857	11/05/2018	18/07/2018	complete
LHAR18-05-01	Harlow	Albert Gardens	S/O 63 on Cycle Track.	Vegetation trimming	Approximately 140 Metres of weed and vegetation growing on Cycle Track needs removing.	3217758	26/04/2018		
LHAR18-06-05	Harlow	Berecroft	Opp L/C: 6770.	HW: overgrown vegetation (our)	Overgrown vegetation overhanging the footway.	3227829	04/06/2018	18/07/2018	complete
LHAR18-05-04	Harlow	Bynghams	In verge O/S 78.	Other (explain in notes)	Wooden Bollard missing. Verge. Topsoil.	20192400	29/01/2015	11/07/2018	complete
LHAR18-05-05	Harlow	Bynghams	R/O 73.	Vegetation trimming	Overgrown Moss covering footway.	3183175	09/01/2018		complete
LHAR18-06-06	Harlow	Bynghams	In verge O/S 78.	HW: bollard missing	Wooden Bollard missing. Verge. Topsoil.	20192400	29/01/2015	20/07/2018	complete
LHAR18-05-06	Harlow	Church End	From R/O 123 to Brookside.	Weeding	Moss on entire Footway.	20379433	12/01/2017		complete
LHAR18-06-07	Harlow	Church Leys	O/S 83.	HW: footway surface defect	0.3 x 0.3 Pointing around S/C. F/W. Flagstone Paving.	3224184	16/05/2018	11/07/2018	complete
LHAR18-06-08	Harlow	Church Leys	O/S 82.	HW: footway surface defect	Approximately 0.3 x 0.3 Pointing around S/C. F/W. Flagstone Paving.	3224183	16/05/2018	11/07/2018	complete
LHAR18-06-09	Harlow	Fennells	F/O 145 to 148.	HW: overgrown vegetation (our)	Overgrown vegetation overhanging the footway.	3230212	06/06/2018	18/07/2018 Done By Others	complete
LHAR18-06-10	Harlow	Fennells	O/S 151 to 154.	HW: overgrown vegetation (our)	Overgrown vegetation overhanging the footway.	3230213	06/06/2018	18/07/2018 Done By Others	complete
LHAR18-06-11	Harlow	Fennells	S/O Garages R/O 1.	HW: footway surface defect	Approximately 0.1 x 0.1 Metre square pointing. F/W. Flagstone Paving.	3230115	06/06/2018	11/07/2018	complete
LHAR18-05-07	Harlow	Gilden Way	Either side of subway.	Other (explain in notes)	Moss covering most of the exposed footway ramps. F/W. DBM.	3147395	30/08/2017		
LHAR18-06-12	Harlow	High Street	S/O 42.	HW: footway structural defect	Approximately 0.15 x 0.8 Metres Square Pointing missing. F/W. Flagstone Paving.	3226192	23/05/2018		
LHAR18-06-13	Harlow	London Road	Around L/C: 6952.	HW: overgrown vegetation (our)	vegetation around lamp column.	3227212	30/05/2018	18/7 Not Rangers Suitable Tree Surgeon Required	UNSUITABLE
LHAR18-05-08	Harlow	Maddox Road	Section alongside Home Close	Other (explain in notes)	approx 12 pcc kerbs displaced and laying in the layby and on footway for collection.	3214851	18/04/2018	01/06/2018	complete
LHAR18-05-09	Harlow	Pyenest Road	O/S 'The Hub @ Harlow' Entrance.	Other (explain in notes)	(Pointing around surface cover). Approximately 0.600 x 0.600 x 0.035mm in places. F/W. Concrete / DBM.	20207004	17/03/2015	01/06/2018	complete
LHAR18-06-14	Harlow	Southern Way	Opp L/C: 4021.	HW: overgrown vegetation (our)	Overgrown vegetation overhanging the footway.	3224871	18/05/2018	18/07/2018	complete
LHAR18-06-15	Harlow	Southern Way	R/O L/C: 4035.	HW: overgrown vegetation (our)	Overgrown vegetation overhanging the footway.	3224874	18/05/2018	18/07/2018	complete
LHAR18-06-16	Harlow	Stony Wood	O/S 23.	HW: verge damaged	Approximately 0.5 x 5.0 Metres Square Verge damaged. Verge. Topsoil.	3226371	24/05/2018	11/07/2018	complete
LHAR18-05-10	Harlow	Tendring Road	O/S 4 Bushey Croft.	Sign cleaning	Road Sign dirty (spray paint).	3209187	05/04/2018	01/06/2018	complete

LHAR18-05-11	Harlow	Tendring Road	Around L/C: 2114.	Vegetation trimming	Overhanging trees restricting double decker busses.	3209160	05/04/2018		complete
LHAR18-05-12	Harlow	The Fairway	Opp 'Luminescence'.	Other (explain in notes)	Salt Bin is Damaged.	3154582	25/09/2017		complete
LHAR18-06-17	Harlow	The Fortunes	R/O 116 - 118.	HW: overgrown vegetation (our)	Overgrown vegetation overhanging the footway.	3221699	08/05/2018	18/07/2018	complete
LHAR18-05-13	Harlow	Tilegate Road	S/O Tilegate House.	Other (explain in notes)	Salt Bin has been damaged.	3155508	28/09/2017		complete
LHAR18-06-18	Harlow	Tripton Road	S/O Steps. S/O L/C: 5199, by underpass.	HW: overgrown vegetation (our)	Overgrown vegetation overhanging the steps / footway.	3227143	30/05/2018	18/07/2018	complete
LHAR18-06-19	Harlow	Westfield	O/S 166 around S/C.	HW: verge damaged	Approximately 0.3 x 0.3 Metres Square Pointing. F/W. Flagstone Paving.	3226880	29/05/2018	11/07/2018	complete
LHAR18-06-20	Harlow	Westfield	O/S 124.	HW: verge damaged	Approximately 1.0 x 5.0 Metre Square verge damage. Verge. Topsoil.	3226911	29/05/2018	11/07/2018	complete
LHAR18-06-21	Harlow	Westfield	O/S 125.	HW: verge damaged	Approximately 2.5 x 5.0 Metres Square Verge damage. Verge. Topsoil.	3226915	29/05/2018	11/07/2018	complete
LHAR18-05-14	Harlow	Woodcroft	Around S/C, O/S 164.	Other (explain in notes)	Approximately 0.3 x 0.3 x 52mm at its deepest point (Pointing). F/W. Flagstone Paving.	3216178	23/04/2018	01/06/2018	complete
LHAR18-05-15	Harlow	Woodcroft	Around S/C, S/O 169.	Other (explain in notes)	Approximately 0.6 x 1.2 x 44mm at its deepest point (Pointing). F/W. Flagstone Paving.	3216182	23/04/2018	01/06/2018	complete
LHAR18-05-16	Harlow	Woodcroft	Around S/C, O/S 169.	Other (explain in notes)	Approximately 0.2 x 0.2 x 32mm at its deepest point (Pointing). F/W. Flagstone Paving.	3216180	23/04/2018	01/06/2018	complete
LHAR18-05-17	Harlow	Woodcroft	Around S/C, O/S 163.	Other (explain in notes)	Approximately 0.3 x 0.3 x 54mm at its deepest point (Pointing). F/W. Flagstone Paving.	3216170	23/04/2018	01/06/2018	complete
LHAR18-05-18	Harlow	Woodcroft	Around S/C, O/S 169.	Other (explain in notes)	Approximately 0.3 x 0.3 x 36mm at its deepest point (Pointing). F/W. Flagstone Paving.	3216179	23/04/2018	01/06/2018	complete