

REPORT 3- HIGHWAY RANGERS

REF	Parish/Ward	Road Name	Location	Type of Work Required	Comments	Confirm Number	Date Requested
LHAR18-08-01	Harlow	Albert Gardens	S/O 63 on Cycle Track.	Vegetation trimming	Approximately 14*0 Metres of weed and vegetation growing on Cycle Track needs removing.	3217758	01/02/2019
LHAR19-02-51	Harlow	Albert Gardens	S/O 63 on Cycle Track.	Vegetation trimming	Approximately 14*0 Metres of weed and vegetation growing on Cycle Track needs removing.	3306518	21/11/2018
LHAR18-08-02	Harlow	Altham Grove	On corner opposite 185	Other (explain in notes)	pcc kerb fallen over 150mms misalignment against adjacent kerbs.	3218341	02/11/2018
LHAR19-02-76	Harlow	Blackbush Spring	O s 140	Other (explain in notes)	Up to 5 pcc bullnose kerbs broken and displaced 2.7 x 150mms	3309751	10/12/2018
LHAR19-02-32	Harlow	Broadfield	S of 115	Other (explain in notes)	3 pcc kerbs broken and misaligned affected area aprox 2.7m	3306932	02/10/2018
LHAR19-02-100	Harlow	Broadfield	S and r of 115	Other (explain in notes)	pcc kerbs misaligned affected area approx 0.9m	3306931	10/01/2019
LHAR19-02-08	Harlow	Broomfield	S of 1c	Other (explain in notes)	pcc kerbs displaced on kerbline ir laying on verge for collection	3261154	05/09/2018
LHAR19-02-97	Harlow	Broomfield	Either s of l c 93	Other (explain in notes)	several sections of broken and displaced pcc kerbs along verge and at kerbline for collecting and disposal	3261152	19/12/2018
LHAR19-02-14	Harlow	Bush Fair	6 Metres from L/C: 7177.	Other (explain in notes)	Pointing Approximately 0*1 x 0*6 x 50mm at its deepest point.	3290477	11/09/2018
LHAR19-02-73	Harlow	Bush Fair	S/O LloydsBank.	Other (explain in notes)	pointing Approximately 0*2 x 1*4 x 58mm at its deepest.	3290081	07/12/2018
LHAR19-02-94	Harlow	Bush Fair	Near L/C: 2806	Other (explain in notes)	Tree grill needs making safe.	3290475	18/12/2018
LHAR18-08-04	Harlow	Bynghams	R/O 73.	Vegetation trimming	Overgrown Moss covering footway.	3183175	04/10/2018
LHAR19-02-60	Harlow	Bynghams	S/O 60.	Weeding	Moss covering most of the footway.	3312992	23/11/2018

REPORT 3- HIGHWAY RANGERS

REF	Parish/Ward	Road Name	Location	Type of Work Required	Comments	Confirm Number	Date Requested
LHAR19-02-21	Harlow	Cambridge Road	Opposite l c 4615 approaching entrance to Fedex building	Other (explain in notes)	section of pcc kerb broken and extending into carriageway by approx 60mms	3283303	11/09/2018
LHAR19-02-20	Harlow	Chamberlain Close	R/O 18.J/W Minton Lane.	Vegetation trimming	Overgrown vegetation causing site line issue.	3325577	11/09/2018
LHAR18-08-09	Harlow	Church End	From R/O 123 to Brookside.	Weeding	Moss on entire Footway.	20379433	11/06/2018
LHAR19-02-36	Harlow	Church Langley Way	Btwn A414 and London rd	Vegetation trimming	veg brambles encroaching onto fw 1.0x90.0M approx dbm	3267092	26/10/2018
LHAR19-02-37	Harlow	Churchfield	Footway leading to garages between 97 and 98	Other (explain in notes)	approx 13.5m pcc kerbs displaced, missing and damaged.Kerbs are spread throughout the length of the footway	3303163	26/10/2018
LHAR19-02-11	Harlow	Coalport Close	O/S 209.	Other (explain in notes)	Pointing Approximately 0.1 × 0.2 × 60mm at its deepest point pointing.	3308644	11/09/2018
LHAR19-02-50	Harlow	Coalport Close	S/O 30 around S/C.	Other (explain in notes)	Pointing - Approximately 0.8 × 1.2 × 32mm at its deepest point.Block Paving.	3308758	21/11/2018
LHAR19-02-05	Harlow	Davenport	R/o no 73.	Vegetation trimming	Tree branches obscuring street lampLC 8951. ?	3292325	03/09/2018
LHAR19-02-44	Harlow	Davenport	R/o no 42.	Vegetation trimming	Tree branches obscuring street lampLC 8948. ?	3292324	02/11/2018
LHAR19-02-115	Harlow	Davenport	R/o no 80.	Vegetation trimming	Tree branches obscuring street lampLC 8983. ?	3292323	05/02/2019
LHAR19-02-06	Harlow	Doulton Close	S/o no 159.	Vegetation trimming	Tree branches obscuring street lampLC 9112. ?	3293297	03/09/2018
LHAR19-02-07	Harlow	Doulton Close	S/o no 131.	Vegetation trimming	Tree branches obscuring street lampLC 9116. ?	3293298	03/09/2018
LHAR19-02-39	Harlow	Doulton Close	S/o no 140.	Vegetation trimming	Tree branches obscuring street lampLC 9114. ?	3293296	29/10/2018
LHAR19-02-33	Harlow	Dunstalls	Opp L/C: 8244	VRGE	Approximately 1.0 × 1.0 × 100mm at its deepest point.	3325533	03/10/2018
LHAR19-02-34	Harlow	Dunstalls	11 Metres from L/C: 9301.	VRGE	Approximately 1.0 × 1.5 × 100mm at its deepest point.	3325530	03/10/2018
LHAR19-02-86	Harlow	Edinburgh Way	Opposite lc 8093	Other (explain in notes)	bollard laying on verge	3284058	12/12/2018
LHAR19-02-26	Harlow	Fesants Croft	S of 79 leading into Mark Hall Moors	Other (explain in notes)	RA3 = 3 × 1 approx 7 kerbs damaged or displaced and laying on the verge for collection	3261172	20/09/2018

REPORT 3- HIGHWAY RANGERS

REF	Parish/Ward	Road Name	Location	Type of Work Required	Comments	Confirm Number	Date Requested
LHAR19-02-72	Harlow	Flex Meadow	13 Metres from L/C: 10660	Sign cleaning	Road sign dirty.	3320112	07/12/2018
LHAR19-02-114	Harlow	Flex Meadow	On traffic island. Opp L/C:10659.	Other (explain in notes)	Unknown Road sign missing.	3320118	05/02/2019
LHAR19-02-90	Harlow	Fourth Avenue	Approaching roundabout with Fifth Avenue	Sign cleaning/ sign amending	30 mph sign laying on verge	3300321	13/12/2018
LHAR19-02-04	Harlow	Great Plumtree	S of 24	Other (explain in notes)	kerb misaligned by 55mms against adjacent kerbs	3263063	06/08/2018
LHAR19-02-47	Harlow	Great Plumtree	Opposite 33	Other (explain in notes)	2cut pcc kerb misaligned by 55mms against adjacent kerbs	3263062	08/11/2018
LHAR19-02-87	Harlow	Great Plumtree	Between 25 and 76 on corner	Other (explain in notes)	3 pcc kerbs misaligned or missing 2.7m total	3263056	13/12/2018
LHAR19-02-88	Harlow	Great Plumtree	Opp and s of 63	Other (explain in notes)	approx 2.7m pcc kerbs broken and displaced.Kerbs are not adjacent.Adjoining footway eroded 0.14in width	3263067	13/12/2018
LHAR19-02-89	Harlow	Great Plumtree	O s 32	Other (explain in notes)	kerb misaligned by 55mms against adjacent kerbs	3263061	13/12/2018
LHAR19-02-99	Harlow	Great Plumtree	O s 26	Other (explain in notes)	kerb misaligned by 45mms against adjacent kerbs	3263057	03/01/2019
LHAR19-02-101	Harlow	Great Plumtree	Opp 76	Other (explain in notes)	6 pcc kerbs damaged and misaligned and adjacent footway spalled and eroded affected area 5.4X 0.3 X 40mms in parts	3263064	10/01/2019
LHAR19-02-111	Harlow	Great Plumtree	Opposite 71	Other (explain in notes)	kerb misaligned by 40mms against adjacent kerbs	3263065	22/01/2019
LHAR19-02-112	Harlow	Great Plumtree	O s 28 and 29	Other (explain in notes)	approx 13 pcc kerbs misaligned or broken affected area 9.1m	3263060	25/01/2019
LHAR19-02-24	Harlow	Hadley Grange	F/O L/C: 5706.	Vegetation trimming	Overgrown vegetation overhanging the footway.	3299742	12/09/2018
LHAR19-02-59	Harlow	Hadley Grange	O/S 8 - 11.	Vegetation trimming	Overgrown vegetation overhanging the footway.	3299636	23/11/2018
LHAR19-02-110	Harlow	Hadley Grange	S/O 19. R/O L/C: 5218.	Vegetation trimming	Overgrown vegetation overhanging the footway.	3299639	21/01/2019
LHAR19-02-62	Harlow	Harberts Road	Opposite 58 Hare Street Springs	Other (explain in notes)	pcc kerb brokenand displaced by 40mms into footway	3296447	23/11/2018
LHAR19-02-69	Harlow	Harolds Road	J/W Elizabeth Way. (North Side).	Sign cleaning	Road signs misaligned on post.	3320794	05/12/2018
LHAR19-02-109	Harlow	Harolds Road	J/W Elizabeth Way. (South Side).	Sign cleaning	Road signs misaligned on post.	3320795	21/01/2019

REPORT 3- HIGHWAY RANGERS

REF	Parish/Ward	Road Name	Location	Type of Work Required	Comments	Confirm Number	Date Requested
LHAR19-02-70	Harlow	Heighams	O/S 43 around S/C.	Other (explain in notes)	Pointing Approximately 0.1 × 0.2 × 44mm at its deepest point.	3311474	05/12/2018
LHAR18-08-16	Harlow	High Street	S/O 42.	Other (explain in notes)	Approximately 0.15 × 0.8 Metres Square Pointing missing .F/W.Flagstone Paving.	3226192	05/12/2018
LHAR19-02-19	Harlow	High Street	O/S 41 around S/C.	Other (explain in notes)	Approximately 50 × 300 × 40mm 'POINTING' at its deepest point.	3322965	11/09/2018
LHAR19-02-85	Harlow	High Street	O/S 46 'Belvoir Estate Agents' around S/C.	Other (explain in notes)	Pointing).Approximately 0.2 × 0.3 Metre Square.F/W.Clay Block Paving.	3283536	12/12/2018
LHAR19-02-18	Harlow	Hobtoe Road	S of entrance to r of Colt Hatch	Other (explain in notes)	pcc kerb broken and displaced by 200mms into carriageway	3316301	11/09/2018
LHAR19-02-116	Harlow	Horsecroft Road	J/W BarrowsRoadto /O L/C: 3753.	Weeding	Moss covering most of the footway.	3321532	05/02/2019
LHAR19-02-15	Harlow	Howard Way	Just before j with Mowbray Road	Sign cleaning	roadsign dirty	3304586	11/09/2018
LHAR19-02-16	Harlow	Howard Way	L c 547	Sign cleaning	roadsigns dirty and moss covered	3304587	11/09/2018
LHAR19-02-17	Harlow	Howard Way	At pelican crossing near church	Other (explain in notes)	2m PGR broken off and laying on verge	3304619	11/09/2018
LHAR19-02-61	Harlow	Howard Way	Appriaching roundabout with First Avenue	Sign cleaning	roadsign dirty and moss covered	3304590	23/11/2018
LHAR19-02-108	Harlow	Jocelyns	O/S 45, around S/C.	Other (explain in notes)	Pointing 0.6 × 0.6 Metre Square pointing.	3301464	18/01/2019
LHAR19-02-13	Harlow	Kiln Lane	Sign post ' 515.	Sign cleaning	Road sign fAdès. .	3303747	11/09/2018
LHAR19-02-57	Harlow	Kiln Lane	R/O L/C: 8593.	Vegetation trimming	RA 6 = 2 × 3.(- Harlow Council).Overgrown vegetation overhanging the footway.	3304166	23/11/2018
LHAR19-02-12	Harlow	Ladyshot	O s flats 176-183	Other (explain in notes)	6 pcc kerbs displaced.	3269011	11/09/2018
LHAR19-02-64	Harlow	Ladyshot	S of flats 26-33	Other (explain in notes)	4 pcc kerbs missing and displaced affected area 3.6m	3269009	26/11/2018
LHAR19-02-104	Harlow	Ladyshot	Opposite 197	Other (explain in notes)	approx 10 pcc kerbs\radius kerbs missing or damaged	3269005	15/01/2019
LHAR19-02-58	Harlow	Little Brays	By bollard & L/C, S/O 123.	Other (explain in notes)	Pointing).Approximately 0.1 × 2.0 Metre Square.F/W.Flagstone Paving.	3259931	23/11/2018

REPORT 3- HIGHWAY RANGERS

REF	Parish/Ward	Road Name	Location	Type of Work Required	Comments	Confirm Number	Date Requested
LHAR19-02-71	Harlow	Little Brays	Opp 73.	Vegetation trimming	Overgrown vegetation around lamp column.	3259981	05/12/2018
LHAR19-02-77	Harlow	Little Brays	Around S/C, O/S 120.	Other (explain in notes)	Pointing).Approximately 0*2 × 0*3 Metre Square.F/W.Flagstone Paving.	3259929	11/12/2018
LHAR19-02-83	Harlow	London Road	Opposite L/C 6947	Sign cleaning/ sign amending	Speed Limit Sign Vandalised	3277797	12/12/2018
LHAR19-02-63	Harlow	Long Ley	Opposite 211	Other (explain in notes)	2 pcc radius kerbs displaced.	3327436	26/11/2018
LHAR19-02-82	Harlow	Long Ley	O s 214	Other (explain in notes)	2 pcc radius kerbs displaced and damaged	3327437	12/12/2018
LHAR19-02-65	Harlow	Maddox Road	O s 27 and 28 Home Close	Other (explain in notes)	pcc kerbs loose and damaged total length 6.3m	3277079	26/11/2018
LHAR19-02-105	Harlow	Maddox Road	O s 26 Home Close	Other (explain in notes)	1 loose pcc kerb 0.9m	3277083	15/01/2019
LHAR18-08-26	Harlow	Malkin Drive	O/S 174.	Other (explain in notes)	Oil Stain on footway(possibly slippery when wet).	3251383	12/12/2018
LHAR19-02-98	Harlow	Mercers	O/S 1.	VRGE	RA 2 = 2 × 1Approximately 2*0 × 20*0 × 100mm at its deepest point.	3316157	20/12/2018
LHAR19-02-67	Harlow	Mistley Road	O s 38-40 Dovehouse Croft	Other (explain in notes)	approx 8pcc kerbs missing or misaligned affected length 7.2m	3263074	29/11/2018
LHAR19-02-113	Harlow	Mistley Road	O s 20 The Chantry	Other (explain in notes)	2 sections of pcc kerbs missing or displaced.100mms difference between rest of kerbline.	3263079	01/02/2019
LHAR19-02-01	Harlow	Momples Road	S of 261 Felmongers	Other (explain in notes)	2 pcc radius kerbs displaced and damaged affected area approx 1.8m	3269456	28/09/2017
LHAR19-02-84	Harlow	Momples Road	O s Steve's Hairdresser in Burgoyne Hatch	Other (explain in notes)	2 pcc kerbs displaced, missing and damaged affected length 1.8m	3269467	12/12/2018
LHAR19-02-25	Harlow	Moor Hall Road	Opp L/C: 3379.	Sign cleaning	Road sign misaligned / obscured by vegetation.	3301570	12/09/2018
LHAR19-02-48	Harlow	Paringdon Road	Opp L/C: 5572	Sign cleaning/ sign amending	Road sign & post misaligned & damaged (faded).	3306027	09/11/2018
LHAR19-02-91	Harlow	Paringdon Road	11 Metres from L/C:5577.Opp St James Church Primary School.	Sign cleaning/ sign amending	Priority Road sign & post damaged (faded).	3306084	17/12/2018
LHAR19-02-92	Harlow	Paringdon Road	L/C: 5591. 20 Metres from J/W Southern Way.	Vegetation trimming	RA 6 = 3 × 2.(- Harlow Council). Street Light obscured by vegetation.	3305877	17/12/2018

REPORT 3- HIGHWAY RANGERS

REF	Parish/Ward	Road Name	Location	Type of Work Required	Comments	Confirm Number	Date Requested
LHAR19-02-93	Harlow	Paringdon Road	S/O 53 Woodhill.	Sign cleaning/ sign amending	2 x Road signs (faded).	3306826	18/12/2018
LHAR19-02-95	Harlow	Paringdon Road	O/S St James School.	Other (explain in notes)	Unknown RoadSign missing from post.	3307977	19/12/2018
LHAR19-02-96	Harlow	Paringdon Road	5 Metres from L/C: 5571.	Sign cleaning/ sign amending	Priority Road signs (faded).	3307907	19/12/2018
LHAR19-02-28	Harlow	Pennymead	Oppositd 35 on bend	Other (explain in notes)	2 pcc radius kerb fallen over 0.9 length	3268575	02/10/2018
LHAR19-02-29	Harlow	Pennymead	Between Pennymead Tower and entrance to garage area	Other (explain in notes)	pcc kerbs displaced and missing affected area approx 2.7	3268583	02/10/2018
LHAR19-02-30	Harlow	Pennymead	O s 67	Other (explain in notes)	pcc bullnose kerb misaligned and ricking when stood on	3268573	02/10/2018
LHAR19-02-31	Harlow	Pennymead	S of 25	Other (explain in notes)	pcc kerb broken in half and moving	3268590	02/10/2018
LHAR19-02-66	Harlow	Pilkingtons	Opp no 39.	Vegetation trimming	Vegetation obscuring street lamp LC 8975. ?	3295585	29/11/2018
LHAR19-02-46	Harlow	Prentice Place	On the corner of Martin's	Other (explain in notes)	pcc kerb broken and partly misaligned by 80mms into carriageway	3282334	07/11/2018
LHAR19-02-27	Harlow	Purford Green	Opp 76	Sign cleaning	Humped crossing sign dirty	3268183	27/09/2018
LHAR19-02-38	Harlow	Rundells	O/S 144 at Base of l/c 3011	Other (explain in notes)	(Damaged).Approximately 0.3 x 0.8 x 30mm in places.F/W.Flagstone Paving.	3277515	29/10/2018
LHAR19-02-107	Harlow	Rye Hill Road	S/O 1 'Laurels' to F/O 2.	Vegetation trimming	Overgrown vegetation overhanging the footway, also moss covering the footway.	3320494	18/01/2019
LHAR19-02-09	Harlow	Second Avenue	L/C: 7657	Sign cleaning	.2 x Road signs dirty.	3261532	06/09/2018
LHAR19-02-74	Harlow	Second Avenue	On lamp pist immediately before the Clock Tower Roundabout	Illegal sign removal	Developers signs fixed to lamppost may need removing.	3301970	10/12/2018
LHAR19-02-52	Harlow	Southern Way	Opp L/C: 3801, around S/C.	VRGE	Approximately 1.5 x 1.5 x 100mm at its deepest point.	3292328	23/11/2018
LHAR19-02-53	Harlow	Southern Way	Opp L/C: 3805,by Underpass.	VRGE	Approximately 1.0 x 1.5 x 100mm at its deepest point.	3292312	23/11/2018
LHAR19-02-54	Harlow	Southern Way	Opp L/C: 3803.	VRGE	Approximately 1.0 x 1.0 x 150mm at its deepest point.	3292326	23/11/2018
LHAR19-02-55	Harlow	Southern Way	Opp L/C: 3804.	VRGE	Approximately 0.6 x 1.5 x 100mm at its deepest point.	3292319	23/11/2018
LHAR19-02-56	Harlow	Southern Way	Between L/C: 3809 & 3810.	VRGE	Approximately 1.0 x 1.0 x 100mm at its deepest point.	3292295	23/11/2018

REPORT 3- HIGHWAY RANGERS

REF	Parish/Ward	Road Name	Location	Type of Work Required	Comments	Confirm Number	Date Requested
LHAR19-02-119	Harlow	Southern Way	Between L/C: 3810 & 3809.	VRGE	Approximately 1•0 × 1•0 × 100mm at its deepest point.	3292294	23/11/2018
LHAR19-02-102	Harlow	Sycamore Field	B/O Flats 190 - 207.	Weeding	Moss covering most of the footway.	3318280	15/01/2019
LHAR19-02-103	Harlow	Sycamore Field	F/O L/C: 9403.	Weeding	Moss covering most of the footway.	3318478	15/01/2019
LHAR19-02-106	Harlow	Sycamore Field	R/O 151 - 153.	Weeding	Moss covering most of the footway.	3319513	17/01/2019
LHAR19-02-02	Harlow	Tending Road	Around L/C: 2114.	Vegetation trimming	Overhanging trees restricting double decker busses.	3209160	05/04/2018
LHAR19-02-22	Harlow	The Chantry	Opposite 51, 52 and 53	Other (explain in notes)	approx. 13.5m of pcc concrete kerbs missing and displaced and adjacent footway eroded in parts height of upstand against eroded footway approx 40mms in parts.	3263602	12/09/2018
LHAR19-02-23	Harlow	The Chantry	O s 52 and 53	Other (explain in notes)	6m pcc kerbs m8ssing or misaligned	3263603	12/09/2018
LHAR19-02-68	Harlow	The Gardiners	S/O 60.	Vegetation trimming	Overgrown vegetation overhanging the footway.	3299492	05/12/2018
LHAR19-02-10	Harlow	The Gowers	S of 15	Other (explain in notes)	pcc kerb misaligned by 100mms.To be removed or reset.	3262596	10/09/2018
LHAR18-08-46	Harlow	The Maples	O/S 136.	Other (explain in notes)	Approximately 0•1 × 0•1 Metre square pointing. F/W.Concret.	3231642	11/06/2018
LHAR19-02-03	Harlow	The Maples	O/S 136.	Other (explain in notes)	Approximately 0•1 × 0•1 Metre square pointing. F/W.Concret.	3231642	11/06/2018
LHAR19-02-45	Harlow	The Stow	R of 104	Other (explain in notes)	approx 7.2m pcc concrete kerbs damaged and displaced	3281336	06/11/2018
LHAR19-02-75	Harlow	The Sweyns	F/O L/C: 3383.	Other (explain in notes)	Pointing 0•2 × 0•2 Metre Square pointing.	3301867	10/12/2018
LHAR19-02-35	Harlow	Third Avenue	Immediately on j with Harberts Road	Other (explain in notes)	pcc radius kerb leaning into carriageway by approx 45mms	3274627	11/10/2018
LHAR19-02-78	Harlow	Tillwicks Road	On L/C: 1162.	Sign cleaning	Road sign misaligned.	3303509	12/12/2018
LHAR19-02-79	Harlow	Tillwicks Road	Opp J/W Tendering Road.	Sign cleaning	2 × Road signs misaligned.	3303510	12/12/2018
LHAR19-02-80	Harlow	Tillwicks Road	11 Metres from L/C: 1694.	VRGE	Approximately 1•0 × 1•0 × 100mm at its deepest point.	3303437	12/12/2018

REPORT 3- HIGHWAY RANGERS

REF	Parish/Ward	Road Name	Location	Type of Work Required	Comments	Confirm Number	Date Requested
LHAR19-02-81	Harlow	Tillwicks Road	S/O Bus Stop / Opp Road Sign '839'.	VRGE	Approximately 1.0 x 1.0 x 100mm at its deepest point.	3303514	12/12/2018
LHAR19-02-117	Harlow	Upper Park	Just before garage access point	Other (explain in notes)	pcc radius kerbbroken and laying on footway.	3310876	03/01/2019
LHAR19-02-118	Harlow	Velizy Avenue	S of l c 10129 on central reservation	Other (explain in notes)	2 pcc kerbs displaced	3283218	08/11/2018
LHAR19-02-49	Harlow	Vicarage Wood	O s 72	Other (explain in notes)	pcc kerb misaligned and adjacent footway damaged affected area approx 1m x 0.9 x 90mms in one part	3290458	21/11/2018
LHAR19-02-40	Harlow	Wych Elm	S of entrance to car wash	Other (explain in notes)	pcc kerb missing and adjacent footway eroded affected area approx 0.9 x 40mms on footway	3278550	02/11/2018
LHAR19-02-41	Harlow	Wych Elm	S of pedestrian entrance to multi storey car park	Other (explain in notes)	6 concrete pcc kerb misaligned	3278552	02/11/2018
LHAR19-02-42	Harlow	Wych Elm	O s Leonard Brooks Paint Specialists	Other (explain in notes)	approx 5 pcc kerbs broken and dispkaced laying against wall of premesis	3278537	02/11/2018
LHAR19-02-43	Harlow	Wych Elm	O s Unit 5	Other (explain in notes)	6 x 5 PCC radius kerb missing and displaced/damaged	3278545	02/11/2018